

Axle / Spindle Nut Torque Specification

BHA53078

Make	Model	Year	Vehicle Notes		Lb. ft	NM
Hyundai	Santa Fe	2001-06		Front	170	230
Hyundai	Tucson	2005-09		Front	Note A	
Kia	Amanti	2004-06		Front	207	281
Kia	Sportage	2005-10		Front	207	281

Note A Tighten hub bearing nut to 202 ft-lbs/274 Nm then hub must be rotated 3 times for secure placement of hub bearing. Unfasten hub bearing nut until its tightening torque is 0 ft-lbs/0 Nm. Hub bearing nut must be fastened again with torque 144 ft-lbs/196 Nm. Assemble split pin. If the direction of split pin is not in line with the hole of knuckle, unfasten hub bearing nut within 30° and assemble split pin

*** Please refer to service manual if your application is not listed**